

Solar Panel must point South.

Drive Self-tapping screws through side of Bands and into post to prevent unwanted rotation and slipping of Solar Panel.

Tools Required




5/16" Nut Driver or Flathead Screwdriver (for Bands)



1/2" Wrench and Ratchet with 1/2" Socket (for Bolts)



■ Square Post mount



Quantity

(4)

(8)

(4)

(2)

Square Post and U-Channel

1-1/2" Pre-threaded Mounting Brackets (2)

5/16" x 4-1/2" All-thread bolts

Item Description

5/16" Washers

1-5/4" - 5" Bands

Self-tapping screws

5/16" Lock Washers 1-34" Round Pipe


5/16" Nuts

(B)

(C)

(J)

¬ U-Channel mount



Round Pole		
Item	Description	Quantity
(G)	1-5%" - 5" Bands	(4)
(F)	Self-tapping screws	(4)
(B)	5/16" Washers	(2)
(H)	5/16" x 3/4" All-thread bolts	(2)
(J)	1-1/2" Pre-threaded Mounting Brackets	(2)

O Round Post mount

